

Canada's Nuclear Regulator

L'organisme de réglementation nucléaire du Canada

Confidential - Prescribed Information

Unclassified Information

ORDER UNDER SECTION 35 OR PARAGRAPH 37(2)(f) OF THE NUCLEAR SAFETY AND CONTROL

ACT

Index no./Order no.	1. CNSC licence no. (if applicable)	2. Date of order (YYYY-MM-DD)	
0495	16494-1-29.1	2024-12-11	
3. Company/licensee (if applicable) and address			
Vision Integrity Engineering Ltd.			
4. Name (and title or position) of person(s) receiving the order			
Chad Leckie (RSO)			
5a. Actions or measures required to be taken by licensee and/or other person(s) (specify) in respect of any facility, place, substance, vehicle, equipment or information (specify), including any time limits or restrictions			
Tavis Cameron, Jeremiah Chartier and McKinley Hyland are hereby ordered stop radiography operations and Vision Integrity Engineering Ltd. is hereby ordered to return exposure devices serial numbers S2460, S3798, S3865 which have been assigned to the McKinley subcontract (Nisku, AB and Grande Prairie, AB) to secure storage at a CNSC approved and disclosed location (Medicine Hat or Lethbridge, AB or storage at a CNSC licensed third party storage facility) until such time that: 1) the CNSC has been informed in writing, of the McKinley subcontract location(s) and the licensee can demonstrate sufficient management oversight and control of the Radiation Safety Program at the location(s). The licensee must specifically demonstrate that: a) sufficient inventory control measures (including inventory tracking, quarterly maintenance, dates & locations of use, pre-operational checks and daily DRD readings) surrounding the three (3) exposure devices have been implemented and, b) calibrated monitoring equipment has been assigned to the three (3) workers currently under the McKinley subcontract and c) the training of the three (3) workers currently under the McKinley subcontract has been completed in accordance with the licensee's established training program OR 2) Vision Integrity Engineering Ltd. has confirmed, in writing, in response to Inspection Report Index DS-16494-JGSL-241211-1 that licensed activities conducted at the McKinley subcontract location have been discontinued.			
Addenda attached			
5b. This order is closed when all terms listed in 5a of this form have been fulfilled, and			
Should Vision Integrity Engineering Ltd. choose Option 2 in box 5a., the response to Inspection Report Index DS-16494-JGSL-241211-1 must demonstrate how Vision Integrity Engineering Ltd. will ensure that the company's Radiation Safety Program will be effectively implemented for any future subcontract relationships it enters into.			
Addenda attached			
6. Information on which order is based			
This order is based on Inspection Report Index DS-16494-JGSL-241211-1 specifically, the licensee's failure to demonstrate that the Radiation Safety Program has been effectively administered for a subcontractor (McKinley) site that has been established in the Nisku, AB (and possibly Grande Prairie, AB) region. The site(s) have not been disclosed to the CNSC, the inventory control (including quarterly maintenance, dates & locations of use, pre-operational checks and daily DRD readings) surrounding the three (3) exposure devices is inadequate and the licensee could not sufficiently demonstrate that calibrated monitoring equipment has been assigned to and training of the three (3) workers currently under the McKinley subcontract has been met.			
Addenda attached			
7. Time limit for complying 🗸 Immediately	Specified time (YYYY-MM-DD)		





8. CNSC inspector or o	lesignated officer making the order		
Name:		Title:	
June Singleton		Inspector	
Address:		Email Address:	
670, 220 - 4 Avenue SE Calgary (AB) T2G 4X3		June.Singleton@cnsc-ccsn.gc.ca	
Telephone:		Fax:	
403-651-3116		(613) 995-5086	
Signature (certificate)	Singleton, June	Digitally signed by Singleton, June DN: C=CA, O=CC, OU=CNSC-CCSN, CN="Singleton, June" Reason: 1 am the author of this document Location: P Date: 2024.12.11 16:05:02-07:00' Foxit PDF Editor Version: 12.1.2	
9. Method of transmitting the order: 🗸 Personal delivery 🗌 Mail 📄 Email 📄 Fax 📄 Other (specify)			
SUMMARY OF SOME RELEVANT SECTIONS OF THE NUCLEAR SAFETY AND CONTROL ACT			
ORDERS OF AN INSPECTOR 35(1) Refer to this subsection for orders issued to licensees. 35(2) Refer to this subsection for orders issued to any person.			
DESIGNATED OFFICERS 37(2)(f) The Commission may authorize a designated officer to make any order that an inspector may make under subsection 35(1) or (2).			
PROCEDURES 38 Every order of an inspector and every order of a designated officer under paragraph 37(2)(f) shall be made, and every measure under paragraph 37(2)(c), (d) or (g) shall be taken, in accordance with the <i>Canadian Nuclear Safety Commission Rules of Procedure</i> .			
COMPLIANCE WITH ORDER 41 Every person named in or subject to an order of the Commission, an inspector or designated officer shall, regardless of whether or not the person has had an opportunity to make representations with respect to the order, comply with the order within the time specified in it or, if no time is specified, immediately.			
OPPORTUNITY TO BE HEARD Refer to sections 39 and 40 of the <i>Nuclear Safety and Control Act.</i>			
LIABILITY FOR COSTS Refer to section 42 of the <i>Nuclear Safety and Control Act.</i>			
OFFENCES AND PUNISHMENT Refer to sections 48 to 65 of the Nuclear Safety and Control Act.			



