



ORDER UNDER SECTION 35 OR PARAGRAPH 37(2)(f) OF THE NUCLEAR SAFETY AND CONTROL ACT

Index No./Order No. OR-14404-RW-250812-1	1. CNSC licence No. (if applicable) 14404-1-26.0	2. Date of order (YYYY-MM-DD) 2025-08-12
3. Company/licensee (if applicable) and address AR Geotechnical Engineering Ltd.		
4. Name (and title or position) of person(s) receiving the order Ayoub Ramadan (President & Applicant Authority)		
5a. Actions or measures required to be taken by licensee and/or other person(s) (specify) in respect of any facility, place, substance, vehicle, equipment or information (specify), including any time limits or restrictions <ul style="list-style-type: none">- The licensee must immediately return the radiation device (S/N: 38288) located in the field to the storage location and contact the Inspector so that the device can be put in the storage job box with the others and a new CNSC tamper-proof seal can be applied to the job box to ensure all devices remain in storage until this Order is closed.- The licensee must ensure that all devices are returned to and remain in storage with the CNSC tamper-proof seal on the storage remaining intact until such time that they possess a CNSC licence which allows use of the radiation devices.- No use of any radiation devices is permitted until such time that the licensee possesses a valid CNSC licence permitting use.		
<input type="checkbox"/> Addendum attached		
5b. This order is closed when all terms listed in 5a of this form have been fulfilled, and <ul style="list-style-type: none">- The licensee has been issued a licence which permits use of the radiation devices.		
<input type="checkbox"/> Addendum attached		
6. Information on which order is based <ul style="list-style-type: none">- The licensee has been performed using the portable nuclear gauges without being in possession of a valid use licence and hence without authorization to do so.		
<input type="checkbox"/> Addendum attached		
7. Time limit for complying <input checked="" type="checkbox"/> Immediately <input type="checkbox"/> Specified time (YYYY-MM-DD) _____		

8. CNSC inspector or designated officer making the order	
Name: Robin Williams	Title: Inspector
Address: Harry Hays Building, 220 4 Ave SE, Calgary, AB T2G-4X3	Email Address: robin.williams@cnscccsn.gc.ca
Telephone: 403-589-6293	Fax: (613) 995-5086

Signature
(certificate)

Williams, Robin



DN: C=CA, O=GC, OU=CNSC-CCSN, CN="Williams, Robin"
Reason: I am approving this document
Edition:
Date: 2025.08.12 15:32:08-06'00'
Foxit PDF Editor Version: 13.0.1

9. Method of transmitting the order: ☐ Personal delivery ☐ Mail ☒ Email ☐ Fax ☐ Other (specify) _____

SUMMARY OF SOME RELEVANT SECTIONS OF THE NUCLEAR SAFETY AND CONTROL ACT

ORDERS OF AN INSPECTOR

35(1) Refer to this subsection for orders issued to licensees.

35(2) Refer to this subsection for orders issued to any person.

DESIGNATED OFFICERS

37(2)(f) The Commission may authorize a designated officer to make any order that an inspector may make under subsection 35(1) or (2).

PROCEDURES

38 Every order of an inspector and every order of a designated officer under paragraph 37(2)(f) shall be made, and every measure under paragraph 37(2)(c), (d) or (g) shall be taken, in accordance with the *Canadian Nuclear Safety Commission Rules of Procedure*.

COMPLIANCE WITH ORDER

41 Every person named in or subject to an order of the Commission, an inspector or designated officer shall, regardless of whether or not the person has had an opportunity to make representations with respect to the order, comply with the order within the time specified in it or, if no time is specified, immediately.

OPPORTUNITY TO BE HEARD

Refer to sections **39 and 40** of the *Nuclear Safety and Control Act*.

LIABILITY FOR COSTS

Refer to section **42** of the *Nuclear Safety and Control Act*.

OFFENCES AND PUNISHMENT

Refer to sections **48 to 65** of the *Nuclear Safety and Control Act*.

